REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

gethering and meints information, including that notwithstending	ining the dete needed g suggestions for rec	 end completing and lucing the burden, to 	f reviewing the collection of infor the Department of Defense, Ex	metion. Send com scutive Services er	ments regere	me for reviewing instructions, searching existing date sources, ding this burden estimate or eny other espect of this collection of cations Directorate (0704-0188). Respondents should be ewere ction of information if it does not display a currently valid OM8		
PLEASE DO NO	T RETURN YOU	R FORM TO TH	E ABOVE ORGANIZATIO	ON.				
	TE (DD-MM-YY) 05-2013	YY) 2. REPO	ORT TYPE Journal Arti	cle		3. DATES COVERED (From - To)		
4. TITLE AND	SUBTITLE				5a. COI	NTRACT NUMBER		
Coating Perfo	mance in Dulu	th Superior Ha	arbor - Part 1					
					5b. GRANT NUMBER			
ļ					5c. PROGRAM ELEMENT NUMBER			
			W56MES00404548					
e MITHORIO					Ed DDG			
6. AUTHOR(S)	and Brenda L	ittle			5d. PROJECT NUMBER			
Tribinara 1. 1.a.)	and Dienda D	11110						
					5e. TASK NUMBER			
					5f. WORK UNIT NUMBER			
						73-9776-00-5		
7. PERFORMIN	G ORGANIZATI	ON NAME(S) AN	D ADDRESS(ES)			B. PERFORMING ORGANIZATION		
Naval Researc						REPORT NUMBER		
Oceanography		****				NRL/JA/733012-1127		
Stennis Space	Center, MS 39	529-5004						
9 SPONSORIA	G/MONITORING	AGENCY NAM	E(S) AND ADDRESS(ES)			10. SPONSOR/MONITOR'S ACRONYM(S)		
			E(S) AND ADDRESS(ES)			U.S. Army		
US Army Engineer District Detroit PO Box 1027						O.S. Ailily		
Detroit, MI 48231-1027						11. SPONSOR/MONITOR'S REPORT		
						NUMBER(S)		
10 5157515117								
	ON/AVAILABILI							
Approved for	public release,	distribution is		12-1	10	~ . ~		
20130613540								
13. SUPPLEMENTARY NOTES								
14. ABSTRACT	vere evaluated f	or correction are	tection of carbon steel s	supons and I-h	name arou	and Duluth Superior Harbor after 46 and 35		
Nine Coatings were evaluated for corrosion protection of carbon steel coupons and I-beams around Duluth Superior Harbor after 46 and 35 months, respectively. Coupons were intentionally scribed to metal before exposure. Part 1 of this article describes the coatings used and the								
locations of coupons and I-beams. Part 2, to be published in the October 2012 issue of MP, will discuss the results of the evaluation								
15. SUBJECT TERMS								
Duluth Superior Harbor, corrosion, barrier coatings								
16. SECURITY CLASSIFICATION OF: 17. LIMITATION OF 18. NUMBER 19a. NAME OF RESPONSIBLE PERSON								
a. REPORT	ARCTRACT			OF	Richard			
Unclassified	Unclassified	Unclassified	UL	PAGES 5	19b. TEL	EPHONE NUMBER (Include area code) (228) 688-4690		

THIS MONTH: CORROSION IN MARINE ENVIRONMENTS

SEPTEMBER 2012

MATERIALS PERFORMANCE

CORROSION PREVENTION AND CONTROL WORLDWIDE

Corrosion Exposure Testing at NASA Launch Facilities

Coating Performance in Duluth Superior Harbor

Corrosion Analysis of a Steel Drinking Water Pipe

Cathodic Protection of Steel Pipe Piles in an Open Sea Environment





Coating Performance in Duluth Superior Harbor—Part 1

RICHARD I. RAY AND BRENDA J. LITTLE, FNACE, Naval Research Laboratory, Stennis Space Center, Mississippi

Nine coatings were evaluated for corrosion protection of carbon steel coupons and I-beams around Duluth Superior Harbor after 46 and 35 months, respectively. Coupons were intentionally scribed to metal before exposure. Part 1 of this article describes the coatings used and the locations of coupons and I-beams. Part 2, to be published in the October 2012 issue of MP, will discuss the results of the evaluation.


ixteen miles (26 km) of carbon steel (CS) sheet piling (12-mm thick A3281 cold rolled; used for docks, bridges, and bulkheads in the Dulnth Superior Harbor (DSH) in Minnesota and Wisconsin are corroding at an accelerated rate of 3 mm/y or higher. Pilings 30 years old or older are riddled with through-wall pitting (Figures 1[a] and [b]).

The corrected pilings have an orange, rusty appearance characterized by tubercles (i.e., corrosion products and deposits covering areas of localized corrosion [Figures 2(a) and (b)]).


Divers reported that tubercles were randomly distributed from the waterline to ~3 m below the surface. Tubercles varied in diameter from a few millimeters to several centimeters and when removed, large and often deep pits were exposed. Divers also reported that the attached zehra mussel (Dressena palymor pha) population was dense and few tubercles were observed below 3 m. Zebra mussels are small, lingernail-sized mussels native to the Caspian Sea. They were first observed in Lake St. Clair, Minnesota in 1988 and have since spread to all of the Great Lakes.

DSH, located at the extreme western end of Lake Superior, is a fresh water harbor with mg/L concentrations of sulfate (SO₁²). DSH is polymitic (i.e., seiches or free-standing wave oscillations are almost always present, suspending particulates into the water column). DSH is icebound from mid-December to mid-April and during that time has a durable, well-defined ice cover. DSH experiences freeze ice thicknesses that range from 0.5 to 1.4 m, as well as snow ice, stack ice, and ice from wave and splash action along harbor walls.


Ray, et al." reported that a combination of hiological, chemical, and physical events contributed to the corrosion of CS pilings in DSH. Deuse deposits of iron-



Corrosion of pilings in DSH. Photos courtesy of Gene Clark, Wisconsin Sea Grant Program.



(a) Wet corrosion tubercles and (b) dry corrosion tubercles on pilings in DSH.



CS coupons in a sample tray at DSH.

TABLE 1



DSH sample locations, CGB-1, CGC-1 (coupons), and the Duluth Seaway Port Authority Facility (I-beams).

TARRET I				
Coupon coatin	g descriptions			
Tray Number: 5 Location: CGB-1 Slot	Sample Designation	Product	Product Chemistry	
1	CGB-1-01	Bare steel		
2	CGB-1-02	Bare steel		
3	CGB-1-03	Bare steel		
4	CGB-1-04	Bare steel		
5	CGB-1-05	1	White two-part solvent- free polyamine epoxy	
6	CGB-1-06	6	White epoxy amine (one coat)	
7	CGB-1-07	7	Black glass flake reinforced epoxy	
8	CGB-1-08	4 .	Green two-part polyamine epoxy-	
Tray Number: 6				
Location: CGC-1 Slot	Sample Designation	Product	Product Chemistry	
1	CGC-1-01	Bare steel		
2	CGC-1-02	Bare steel		
3	CGC-1-03	Bare steel		
4	CGC-1-04	Bare steel		
5	CGC-1-05	.4	Green two-part polyamine epoxy	
			Red urethane micacoous iron oxides/refined coal	
6	CGC-1-06	5	lar	
7	CGC-1-07	9	Blue/grey zinc primer/ vinyl copolymers	

oxidizing bacteria produced tubercles. creating conditions for Cu precipitation on CS surfaces. Ice scoring disrupted the tubercles and exposed localized areas of Cu-covered CS to uxygen (Oa). The resulting galvanic cell produced aggressive localized corrosion. Barrier coatings provide and aprion for protection of extensive structures in fresh water. Al Beitelman (retired), former director of the Paint Technology Center at the U.S. Construction Engineering Research Laboratory (CERL) (Champaign, Illinois), selected the following coatings for this evaluation (hereafter referred to by their corresponding numbers):

- 1 Aquapure HR!
- 2 Chevron Phillips TZ9043
- 3 Coal tar epoxy
- 4 Humidur ML!
- 6 Wasser MC-zine/MC-tar
- 6 Sherwin-Williams Fast clad CR*
- 7 Sherwin-Williams Sher glass epoxy¹
- 8 Standard epoxy
- 9 Zinc-rich printer VZ108/V766

Methods and Materials

Divers from AMI Consulting Engineers (Superior, Wisconsin) installed trays for coupons and I-beams. Eight sample trays containing eight 4.5 by 7.5 by 1.2-in (114 by 190 by 30-mm) thick A328 steel sample coupons per tray (Figure 3) were prepared.

Each sample tray contained four coated and four uncoated steel coupons. A report[§] prepared for the U.S. Army Corps of Engineers provides details about tray and coupon installation. Trays and coupons were installed on November 7, 8, and 13, 2007. Coupons were retrieved from two locations, U.S. Coast Guard Cell B (CGB-1) and U.S Coast Guard Cell G (CGG-1) (Figure 4) on September 20, 2011. Table 1 presents coupon coating descriptions.

Trays designed to contain 1-beans, 6 by 7 174 by 36 in (152 by 184 by 914 mm), were prepared (Figure 5) and installed at the Duluth Seaway Port Au-

White two-part solventfree polyamine epoxy

CGC-1-08

[&]quot;Frade name.

thority Facility (Figure 4) in September 2008. Table 2 provides I-beam coatings descriptions.

I-beams were retrieved from the original location at the Duluth Seaway Port Ambority Facility in Jate August 2010 and submerged in plastic barrels for outside storage through one more winter. They were sent to the U.S. Naval Research Laboratory at Stennis Space Center (Mississippi) in October 2011,

Summary

A combination of biological, chemical, and physical events have contributed to accelerated corrosion of 16 miles of CS sheet piling in DSH. A series of coatings were tested on CS coupons and I-beams to evaluate their effectiveness in preventing the localized corrosion, Part 2 of this article, to be published in October 2012 MP, will detail the results of the coatings evaluation.


References

- ASTM Standard A328/A328M-07, "Standard Specification for Steel Sheet Piling" (West Conshohocken, PA: ASTM International, 2007).
- 2 R. Ray, J. Lee, H. Little, "Factors Contributing to Corrosion of Steel Pilings in Duluth Superior Harbor," Сытыя 65 (2011); рр. 707-717.
- 3 "ACOE Sample Tray Installation," AMI Consulting Engineers, Project #071097. December 2007.

RICHARD I. RAY is a physical scientist at the Naval Research Laboratory, Code 7332, Stennis Space Center, MS 39529-5004. He has worked for the Neval Research Laboratory for 29 years, operating scanning electron microscopes for research on biodeterioration and biodegradation of materials in marine environments. He has a B.S. degree in biology from the University of Southern Mississippl and received four Alan Berman Research Publication Awards and the Sigma XI Award.

BRENDA J. LITTLE, FNACE, is a senior scientist at the Naval Research Laboratory. She uses surface analytical chemistry, electron microscopy, and electrochemical techniques to investigate adsorption, biofouling, biodegradation, bioremadistion, and corrosion in marine environments. She is a NACE International Fellow and has been a NACE member since 1984. MP

FIGURE 5



I-beam sample tray design and Installation.

ım coating descriptions

TABLE 2

The Company of the State of the Company of the Comp					
Sample No.	Product	Product Chemistry			
1	1	White two-part solvent-free polyamine epoxy			
10	1				
2	2	Light green/white two-part epoxy			
11	2				
3	3	Grey two-part coal tar polyamide epoxy			
12	3				
4	4	Green two-part polyamine epoxy			
13	4				
5	5	Red urethane micaceous iron oxides and			
14	5	refined coal tar			
6	6	White amine epoxy (one coat)			
15	6				
7	7	Black glass flake reinforced epoxy			
16	7				
8	8	Black two-part polyamide epoxy/zinc primer			
17	8				
9	9	Blue/grey zinc primer/vinyl copolymer			
18	9				



MP Buyers Guide Online

Visit the 2012 MP Buyers Guide Online, www.mpbuyersguide.com, for instant occess to thousands of companies and consultants providing the latest in corrosion control products and services. If your company is not yet included, you can add and then edit your listing at any time throughout the year.

MATERIALS PERFORMANCE

CORROSION PREVENTION AND CONTROL WORLDWIDE

NACE INTERNATIONAL

SEPTEMBER 2012

VOL. 51 NO. 9

SPECIAL FEATURES

- 28 NASA Launches Study of Corrosion Exposure Testing Kathy Riggs Larsen
- 76 Company Showcase

CATHODIC PROTECTION

- 34 Cathodic Protection of Steel Pipe Piles in an Open Sea Environment 1: Miyata and 1: Akira
- 41 CP Blog

COATINGS & LININGS

- 45 Amine Blush Testing Part 2 Melissa Tuchscherer
- 48 Coating Performance in Duluth Superior Harbor—Part 1 Richard I. Ray and Brenda J. Little, FVACE
- 52 Cl. Blog

CHEMICAL TREATMENT

58 CT Blog

MATERIALS SELECTION & DESIGN

- 62 Gorrosion Analysis of a Steel Drinking Water Pipe in an Indoor Environment
 Lingling Wang, Nuc Lin, Linxia Fang, Thirci Wu, and Huijuan Chen
- 66 Aluminum Oxide Nanoparticles in Cement Mortar Muhammad Reza Arefi and Zohair Sarajan
- 71 MSD Blog

About the Cover

The Beachside Corrosion Test Sita at NASA's John F. Kennedy Space Center (KSC) Beachside Atmospheric Corrosion Test Facility includes 600 ft (183 m) of test racks located 100 ft (30 m) from the Atlantic Ocean and ~1 mile (1.6 km) from KSC's rocket launch sites. The NASA Corrosion Technology Laboratory at KSC leunched a study of corrosion exposure testing to determine if a correlation could be made between marine atmospheric exposure tests end eccelerated corrosion tests. See the feature article on p. 28. Photo courtesy of NASA.





THE CORROSION SOCIETY

02012 NACE International